

Work Order ID 60855

Monday, July 26, 2010 10:51:30 AM



Page 1

Item ID: D2596

Accept



Setup Start



Revision ID:

Stop



Item Name: Web, 205 Skidtube

Start Date: 7/26/2010 Start Qty: 4.00



Cust Item ID:

Required Date: 8/3/2010 Req'd Qty: 4.00



Customer:

Reference:

Run Start



Approvals: Process Plan: *R*

Date: *10/7/28*

Tooling:

Date:

Stop



QC:

Date:

SPC (Y/N):

Date:

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D2596

Rev D

100

0.00



Skidtubes

Skidtubes

Memo

0.00

Skidtubes

1- Cut D2500-3-100 to length: 99.5"
2- Use Jig DT8093 to drill pilot holes #30
3- Open to 0.630" diameter as per Dwg D2596
4- Deburr

M 10/7/28

(4)

110

Chemical Conversion Coat per QSI005 4.1

0.00



HandFinish

Memo

0.00

Hand Finishing

M 10/7/28

(4)

120

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

5 10/7/28

(4)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DCA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 60855

Monday, July 26, 2010 10:51:30 AM

Page 2

Item ID: D2596

Revision ID:

Item Name: Web, 205 Skidtube

Start Date: 7/26/2010 Start Qty: 4.00

Required Date: 8/3/2010 Req'd Qty: 4.00

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Accept

Setup Start

Stop

Run Start

Stop

Cust Item ID:

Customer:

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130 Packaging Packaging	Identify as per dwg & Stock Location: <u>LG.</u> Memo	0.00 0.00		(4)		11/19/7/28			
140 QC Quality Control	QC21- Final Inspection - Work Order Release Memo	0.00 0.00							10/07/29 JA 10-7-25 (4)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DCA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Monday, July 26, 2010 10:51:35 AM

Page 1

Work Order ID: 60855



Parent Item: D2596



Parent Item Name: Web, 205 Skidtube


Start Date: 7/26/2010

Required Date: 8/3/2010

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP: D□99.02.02□Changed QA to QC, Added Step 6 and Cost□DM
IPP Rev:E 07-07-09 Incorporated DEO 9183 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2500-3-100 		Manufactured	No			100	Each	105.0000	1	4			

Ext'n - I Beam Web 4"

Location

Loc Qty

Loc Code

LG

105

51957

105

4 M 10/7/20

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DCA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries

DART

DESIGN <i>PH</i>	DRAWN BY <i>PH</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2596	REV. D SHEET 1 OF 1
DATE 07.04.17		TITLE 205 WEB	SCALE 1:20
A	96.09.16	NEW ISSUE	
B	97.07.23	Ø0.63 HOLE WAS Ø0.56	
C	98.09.14	INCORPORATED DEO 9097	
D	07.04.17	INCORPORATED DEO 9183	

RELEASED
07.06.18

ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 60855

**D2596 WEB**

- 1) MATERIAL: MAKE FROM D2500-3-100 EXTRUSION
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) DEBURR SHARP EDGES 0.010 TO 0.020

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:			WORK ORDER CHANGES					
DATE	STEP		PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries